

Site Visit Report

Project: Illusion Building 101

Date: 21/03/2024



All Tickets: -15
Open Tickets: - 14

Table of contents

Cracked tile joint (1)	3
Water insulation went of the wall (2)	4
Badly done grouting (3)	6
Empty sound under the tile (4)	8
Not finished tile work under and behind the washbasin (5)	10
Hole in the ceiling (6)	12
70 percent tiles have empty sound (7)	14
Badly done tile measuring (8)	15
Not closed hole or way big wooden cover (9)	17
Badly done paintwork (10)	19
Missing decorative skirting (11)	21
Missing grouting (12)	23
Floor levelled checked (13)	25
Holes in the joints (14)	27
Missing caps at the aluminium profile (15)	29

ID:1 **Title: Cracked tile joint**

Status:Open

Date:21/03/2024
Layer:L3 plan

Type of Works: Tiling

Works: Defect

No Plan Position set	No Plan Position set
----------------------	----------------------



Comments: Parking

Instructions:

ID:2 Title: Water insulation went of the wall

Status:Open

Date:21/03/2024
Layer:L3 plan

Type of Works: Construction

Works: Defect



Comments: Parking
Redo the insulation

Instructions:

ID:3 Title: Badly done grouting


Status:Open

Date:21/03/2024

Layer:L3 plan

Type of Works: Tiling

Works: Defect



Comments: Guest toilet

Instructions:

ID:4 Title: Empty sound under the tile


Status:Open

Date:21/03/2024

Layer:L3 plan

Type of Works: Tiling

Works: Defect



Comments: Guest toilet
Walls are OK

Instructions:

ID:5 Title: Not finished tile work under and behind the washbasin


Status:Open

Date:21/03/2024

Layer:L3 plan

Type of Works: Tiling

Works: Defect



Comments: Guest toilet

Instructions:

ID:6 Title: Hole in the ceiling


Status:Open

Date:21/03/2024

Layer:L3 plan

Type of Works: Painting

Works: Defect



Comments: Guest toilet

Instructions:

ID:7 **Title: 70 percent tiles have empty sound**

Status:Open

Date:21/03/2024

Layer:L3 plan

Type of Works: Tiling

Works: Defect

No Plan Position set	No Plan Position set
----------------------	----------------------



Comments: All flat (possible crack in case of dropping something heavy)

Instructions:

ID:8 Title: Badly done tile measuring


Status:Open

Date:21/03/2024

Layer:L3 plan

Type of Works: Tiling

Works: Defect





Comments: Main hall

Instructions:

ID:9 Title: Not closed hole or way big wooden cover


Status:Open

Date:21/03/2024

Layer:L3 plan

Type of Works: Carpenter

Works: Defect



Comments: Main hall

Instructions:


ID:10 Title: Badly done paintwork

Status:Open

Date:21/03/2024
Layer:L3 plan

Type of Works: Painting

Works: Defect



Comments: Kitchen

Instructions:

ID:11 Title: Missing decorative skirting


Status:Open

Date:21/03/2024

Layer:L3 plan

Type of Works: Carpenter

Works: Damage



Comments: Kitchen hood

Instructions:

ID:12 Title: Missing grouting


Status:Open

Date:21/03/2024

Layer:L3 plan

Type of Works: Tiling

Works: Defect



Comments: Bedroom 1

Instructions:


ID:13 Title: Floor levelled checked

Status:Resolved

Date:21/03/2024
Layer:L3 plan

Type of Works: Tiling

Works: General works



Comments: Ok

Instructions:

ID:14

Title: Holes in the joints


Status:Open

Date:21/03/2024

Layer:L3 plan

Type of Works: Construction

Works: Defect



Comments: Veranda.

Instructions: Fix with any polymeric concrete repairing material (f.a. - BS18)

ID:15 Title: Missing caps at the aluminium profile


Status:Open

Date:21/03/2024

Layer:L3 plan

Type of Works: Windows

Works: Defect



Comments: Veranda

Instructions:

